O	OB WO OZZ PURCHASE ORDER CHANG	04-45618-007
	PROJECT: MODIFY PACKING GLAND	DATE:
	FCO #: 015	PROJECT #: 80960
1	CUSTOMER: IPSC	P.O. #:
	REASON FOR CHANGE:	
	IPSC REQUEST	
T	DESCRIPTION OF CHANGE:	,
E		
1	MODIFY NEW BURNER TO RECEIVE SCANNERS	
_		
P	PEOPLE CONTACTED AND METHODS TAKEN TO	O PESOLVE PROBLEM:
-	IPSC - HOWARD HAMILTON	O RESOLVE PROBLEM.
	1 - DRILL HOLES	
T	2 - TAP HOLES & INSTALL BOLTS	
ó	2 - TAP HOLES & INSTALL BOLTS	
N	("X" APPROPRIAT	TE BOX)
	FIRM PRICE: TIME & MATERIAL:	X NOT TO EXCEED:
	TEI SIGNATURE:	LABOR: \$ 8,956.96
	DATE:	MATERIALS: \$ 400.00
	RECEIVED BY:	OTHER: \$
	DATE:	TOTAL: \$ 9,356.96
C	EXISTING APPROVED PURCHASE ORDER:	\$
บ	THIS FCO:	\$
S	OTHER APPROVED FCO'S:	\$
T	NEW PURCHASE ORDER:	 \$
0	BY SIGNATURE BELOW, TEI IS AUTHOR	RIZED TO PROCEED ON ABOVE
M	REFERENCED CHANGE, TO THE ORIGINAL	
Ε	PRICE AND CONI	DITIONS.
R		
Α	CUSTOMER COORDINATOR	PROJECT MANAGEMENT
Р	APPROVAL:	APPROVAL:
P	SIØNATURE:	SIGNATURE:
R		1/ hand to the
0	Had Julin	1 Sugues Touck
٧	DATE:	DATE:
Α	0//2	3-7-04

TEI CONSTRUCTION SERVICES, INC.

TEI Construction Services, Inc. T&M Billing Cost Summary

PROJECT: Client: Intermountain Power Plant Progress Energy PO#: TEI PROJECT: 80960 TEI FCO#: EWO-015 **LABOR** Week Ending Hours **Amount** 99 \$3,720.65 \$3,720.65 **Totals** 99 **TOTAL LABOR** \$3,720.65 **SMALL TOOLS & CONSUMABLES Cost Per Hour** Amount Hours \$3.75 \$371.25 99 \$371.25 **TOTAL SMALL TOOLS & CONSUMABLES** MATERIAL Vendor PO# Invoice # **Amount** Sub Total \$0.00 10% Mark-Up \$0.00 \$0.00 **Total Material SUBCONTRACTORS** PO# Amount Invoice # Vendor Sub Total \$0.00 \$0.00 10% Mark-Up \$0.00 **Total Subcontractors RENTAL EQUIPMENT** PO# Invoice # Amount Vendor \$0.00 Sub Total 10% Mark-Up \$0.00 \$0.00 **Total Rental Equipment** Description Rental Period **Amount**

TOTAL BILLING

Total TEI Rental Equipment

\$0.00

\$4,091.90

TEI Construction Services, Inc. T&M Billing Weekly Labor

PROJECT 80960 CLIENT INTERMOUNTAIN POWER PLANT TEI NO. ORDER NO. EWO NO. 015

CRAFT CLASS	ST HOURS	@	TOTALS	OT HOURS	@	TOTALS
Superintendent	1.00.00	\$66.88	\$0.00		\$93.67	\$0.00
General Foreman		\$46.65	\$0.00	,	\$67.32	\$0.00
Foreman		\$43.59	\$0.00		\$62.72	\$0.00
Cert Welder	76	\$33.67	\$2,558.92	23	\$50.51	\$1,161.73
	1 70	\$33.67	\$0.00		\$50.51	\$0.00
Mechanic		\$27.55	\$0.00		\$41.33	\$0.00
Apprentice Helper		\$24.49	\$0.00		\$36.74	\$0.00
Laborer		\$18.37	\$0.00		\$27.55	\$0.00
Field Clerk		\$42.06	\$0.00		\$60.43	\$0.00
TIELU OICIK		12.00				
TOTALS	76		\$2,558.92	23		\$1,161.73

TOTAL BILLING

\$3,720.65


	•	DESCRI	DESCRIPTION OF WORK PERFORMED	ORK PERFC	RMED								
CONSTRUCTION SERVICES, INC.		modify Part											
LY TIMESHEET		Packing											
YIDATE: J. db-o4 - Thur		gland											
FT: Tam (Meshee)													
<<< JOB NUMBERS >>>		015										TOTA	TOTALS
1P# EMPLOYEE	CRAFT	ST/OT	ST/OT	ST/OT	ST/OT	10/18	ST/OT	ST/OT	ST/OT	ST/OT	ST/OT	ST/OT	PD DAYS
). a	Mech	114	1	1	/	1	/	/	_	_	/	4/1	
Gentry	Mach	218	1	1	1	1	/	/	_	/	/	812	
Finlason	MACH	218	1	/	/	1	/	/	1	/	/	812	
		/ /	_		/	/	/	/	1	1	1	/	
			_	/	_		/	/	1	1	/	/	
		\	/	/	_		/	/	/	1	/	/	
		-	/	/	_	_	_	1	/	/	/	/	
			/	_	/	/	/	1	1	1	1	/	
)	_		/	_	/	/	/	/	/	/	
		>	/	_	/	_	/	/	/	/	/	,	
		~	/	/		_	/	/	/	/	/		
		<	_	^	/	1	/	1	1	1	/	/	
X		1	/	/	/	1	1	1	1	1	/	/	
		\setminus	/	1	/	1	1	1	1	1	1	1	
			/	/	1	/	/	/	1	_	/	_	
		//	/	/	/	/	/	1	1	/	/	_	
		//	/ /	1	/	1	1	/	/	/	1	1	
			/ /	/	/	/	1	/	/	/	/	1	
		_	//	. /	1	1	/	,	/	/	1	1	
		\	\	/	/	/	/	_	_	/	1	1	
		/ /	V	/	/	1	/	/	/	1	1	1	
		_ / /	/	1	/	1	/	1	1	/	1	1	
TOTALS		2015	1	1	1	1	1	1	1	/	1	2015	
2 1114411 7	Fred.		Equipment:				:						i
Approval:	2	1											
stomer Approval:	M	<u>.</u>	Material:										


stomer Approval:

DESCRIPTION OF WORK PERFORMED Modify CONSTRUCTION SERVICES, INC. Pack ing Gland LY TIMESHEET YIDATE: FRI - 2-21-04 FT: 1/5 T & M TIMESHEET <<< JOB NUMBERS >>> 015 TOTALS EMPLOYEE CRAFT ST/OT IP#I ST/OT PD DAYS 812 Thomas Farrar mech 812 Mech 812 John mech **TOTALS** Approval:_

	_
	-
	-
The State of the S	
***************************************	_

			PTION OF V	VORK PERF	ORMED				,				
CONSTRUCTION SERVICES, INC.		Modify Packing											
LY TIMESHEET		Gland											
11DATE: 700,-1-24-04													
FT: T & M THMESHEET		EXTRA											
<<< JOB NUMBERS >>>		015										тот	ALS
P# EMPLOYEE	CRAFT	ST/OT	ST/OT	ST/OT	ST/OT	ST/OT	ST/OT	ST/OT	ST/OT	ST/OT	ST/OT	ST/OT	PD DAYS
George Gentry	mech-	812	1	1	1	1	1	1	1	1	1	8 1z	
Dylan Finlason	mech.	812	1	1	1	1	1	1	7	1	1	812	
		\·- / /	1	1	1	1	1	1	1	1	1	1	
			1	1	1	1	1	1	1	1	1	1	
					1	1	1	1	1	1	1	/	
		1//	1	1	1	1	1	1		1	1	1	
		1//	1	1	1	/		/	1	1	1	1	
		11	1	1	1	1	1	1	1	1	1	1	
		111	1	· /	1	1	1	1	1	1	1	/	
	<u> </u>		/	1	1	1	1	1	1	1	1	/	
	_A	<u> </u>	/	1	1	/	1	/	1	1	1	1	
		1 1/	1	1	1	/	1	1	1	1		1	
A		1//	1	1	1	1	1		1	1	/	1	
		1 / 1	/	/		/	1	1	1	1	/	/	
	 	<u> </u>	/	/	1	/	1			1	/	/	
		 	/	/	1		/	/	1	1	1	1	
		 // //	1	1		/	/	/	1	1	1	/	
	 	11/1	1	1				/	/	1	1	1	
	//	11/	/	- /	/_	/	/	/	/	1	1	/	
	/		/	/	/			/	/	1	1	1	
		1 1/	\ /	1.		/	/			1	1	1	
707110		1 1	\ /	1	1	1	/	/	/	1	/	1	
TOTALS		1614	\ /	1			<u> </u>		/	1	1	1	
Approval: Minul His	161	, +/	Equipment	<u>:</u>		-							
stomer Approval:	M		Material:			- -							





TERMOUNTAIN POWER SERVICE CORP. (435) 864-4414 - Purchasing FAX (435) 864-6678

MOBILE, AL

/ENDOR: TEI CONSTRUCTION SERVICES INC.

7870 SCHILLINGER PARK WEST

36608

PURCHASE ORDER

01 MAR 2004

VENDOR MUST SHOW PO NUMBER ON ALL INVOICES, BILL OF LADING CORRESPONDENCE, AND ON PACKING LISTS IN EACH CONTAINER, TO INSURE PROMPT PAYMENT CHARGES FOR TRANSPORTATION MUST BE SUPPORTED BY COPY OF FREIGHT BILL PURCHASE ORDER NO. VENDOR CODE REQUISITION NO

T O

04-45618-007

8149

* * *

200606

INTERMOUNTAIN POWER SERVICE CORPORATION 850 W. BRUSH WELLMAN RD.

DELTA , UT 84624-9546

SHIP

251-633-4181 OR 864-879-6860

FIRMING DO	NON CONFIRMING	SHIP VIA	1	FOB POINT	PAGE	
DUPLICATE	COM Mining X	VENDOR TRUCK	AS INVOICED	DESTINATION F/A	1 % 1	FAX

ANTITY	U M	IPSC PART NO.	DESCRIPTION	ACCOUNT NUMBER	UNIT PRICE	EXTENSION
	EA		LINE 1	2SGX-402 03-96033-22	9,356.00	9,356.00
			DATE REQUIRED 02/27/04		TOTAL COST	9,356.00

voices and correspondence may be mailed to Intermountain Power Service torporation, 850 West Brush Wellman Rd., Delta, Utah, 84624-9546.

:knowledgement is required if shipment will not be made within FIVE days.

ark packages or items with IPSC part number and/or P.O. Line number. how number on invoice and packing slip.

andor must furnish applicable material safety data sheets.

ederal taxes. ld to invoice all applic

UTAH VENDORS ARE TO ADD TO THE INVOICE ALL APPLICABLE STATE, AND COUNTY TAXES.

OUT OF STATE VENDORS, LICENSED TO COLLECT UTAH TAXES. ARE TO ADD TAX OF 6%

UTAH TAXES WIT "F. ACCRUED BY IPSC FOR OUT OF STATE ORS NOT LICENSED TO COLLECT UTAH . . . E TAX

NANCY BENNETT 435-864-4414

REVIEWED BY NANCY BENNETT

550-B Brookshire Rd Greer, SC 29651

PAGE 03/18/04 DATE ShannonE **BUYER**

COMPANY TRUCK

Phone: 864-879-4800 864-879-3530 Fax:

SHIP VIA DESTINATION F.O.B.

NET 30 **TERMS**

N D 0 R

107823 INDUSTRIAL SUPPLY 1635 SOUTH 300 WEST SALT LAKE CITY UT 84115 USA

103 TEI CONSTRUCTION SERVICES C/O INTERMOUNTAIN POWER 850 WEST BRUSH WELLMAN ROAD DELTA UT 84624-9546 USA TINKER STEEDE 251-633-4181

FAX: 801-487-0469

EASE ACCEPT OUR ORDER AND FURNISH THE FOLLOWING, SUBJECT TO CONDITIONS BELOW, ON THE REVERSE SIDE OF THIS P/O.

REMIT TO:

INDUSTRIAL SUPPLY P.O. BOX 30600 SALT LAKE CITY UT 84130 USA

OUR ORDER NUMBER MUST APPEAR ON INVOICE, B/L BUNDLES, CASES, PACKING LIST AND CORRESPONDENCE

PURCHASE ORDER ENO-015

PROJECT NO.

ACCOUNT NO.

FAX SENT PRIOR DO NOT DUPLICATE ☐ VERBAL PLACED PRIOR DO NOT DUPLICATE

QTY. ORDERED QTY. DUE ITEM DESCRIPTION UNIT PRICE / EXT. PRICE MISC SUPPLIES 280.64000 1 1.000

1.000

03/10/04

ORDER# 1390026-0001-01

EWO-015

FELLER TO ACHNOWLEDGE THIS ORDER BY SIGNING AND RETURNING O THE ADDRESS ABOVE-ATTEN:A/P DEPT (FAX 864-879-6448)

DATE

Total:

USD280.64

280.64

US DOLLARS

8 8000am 03-18-04

Warn W Sturb

PURCHASE / MATERIAL REQUISITION

Page ____ Of ____

Date	Ordere	:d: /	wett-3-10-04	Job#:	80960	PO#	960262
Vend	or: 🕆	nd 9 1078=	Ylddn	-	Contact: Phone # Fax #:	1 1	
Ship '	Го: ¬	El		-	Phone #	Ewo01.	5
Requi	sitione obera	ed By:	Date Required:	10.04	Terms:	Ship	Via:
Item#	Qty	Units	_{Shar} k Descrip	tion		Cost / Unit	Extended Price
1	04	εA	3/4 TAPSNE	ThREA	O BUSNEY	s 24-88	99.52
2	2	εA	3/4 TAPSNE 2" Standard NC	Dies-	7FA	7.28	14.56
ρſ	(EA	Tax			lp.56	6.56
4	1	EA	Freignt			•	160.00
			. 3				120.00
							280.44
							, i
				· · · · · · · · · · · · · · · · · · ·			
			Order # 139002	/ A Da	1-01		
			:	0 000	:		
			*				
						_	
				·····			
 	·	//				······································	

Authorized Signature

NDUSTRIALSUPPLY

The real difference between companies is the way treat their customers.

CUSTOMER NUMBER

TEI100

Packing Slip

ORDER NUMBER

1390026-0001-01

SHIP TO: TEI CONSTRUCTION SERVICES 850 W. BRUSH WELLMAN RD

DELTA, UT 84624

BILL TEI CONSTRUCTION SERVICES
TO: 550 B BROOKSHIRE RD
GREER, SC 29651
864 879-4800

SHIP/TR/INVOICE NO	SLMAN	ORDER DATE	TAKER	CUSTOMER P.O. NUMBE	R		DATE
1390026-0001-01	113	3/10/04	161	960-262		3	/10/04
		INSTRUCTIONS	;		ROUTE	FRT	PAGE NO
DELIVER TODAY SUR	E				90	В	1

	QUANTITY	CUIDDED	DISP	.U/M	ITEM CODE AND DESCRIPTION	UNIT PRICE	AMOUNT
ORDERED 4	BO/RET	SHIPPED 4	*	EA	CALL FOR MSDS SHEETS CHEM SPILLS CALL 800-424-9300 UTD 1500T 3/4-10 TAP 4 FLUTE HAND GT/HSS H3 UTD 1010139 1-990231	24.8800	99.52
2		2	*	EA	HRD 1/2-13 DIE HEX RETHREADING CT/CS ACE 7244 NC 1-990226	7.2800	14.56

SHIP ORDER**

*** ORDER COMPLETED ***

DISP CODE:

- STATE TAX APPLICABLE B ALANCE BACK ORDERED

ONSIDER COMPLETE

IRECT SHIPMENT F -

PRINT NAME

ACTORY MINIMUM

SUB TOTAL 114.08
MISC. CHARGE 0.00
FREIGHT TOTAL 0.00
STATE TAX 6.56
PAYMENT REC'D 0.00

TOTAL 120.64 280.64

TO INSLIRE PROPER CREDIT PLEASE INCLUDE THIS PACKING SLIP WITH RETURNS.

P7 03062

INTERMOUNTAIN POWER SERVICE CORP. (435) 864-4414 - Purchasing FAX (435) 864-6678

MOBILE, AL

VENDOR: TEI CONSTRUCTION SERVICES INC.

7870 SCHILLINGER PARK WEST

36608

PURCHA E ORDER

01 MAR 2004

VENDOR MUST SHOW P 0 NUMBER ON ALL INVOICES, BILL C DENCE, AND ON PACKING LISTS IN EACH CONTAINER, TO IN CHARGES FOR TRANSPORTATION MUST BE SUPPORTED BY DING CORRESPON-PROMPT PAYMENT. PURCHASE ORDER NO. VENDOR CODE

OF FREIGHT BILL. REQUISITION NO

04-45618-007

8149

200606

SHIP T O * * * INTERMOUNTAIN POWER SERVICE CORPORATION 850 W. BRUSH WELLMAN RD. DELTA , UT 84624-9546

251-633-4181 OR 864-879-6860

OCCUPIED MILE DO	INON					
CONFIRMING DO NOT DUPLICATE	NON CONFIRMING v	SHIP VIA	TERMS	FOB POINT	PAGE	\
NOT DOPLICATE	CONFIRMING X	VENDOR TRUCK	AS INVOICED	DESTINATION F/A	1 ^{OF} 1	FΛΥ
				220111111111111		LAX

INTERMOUNTAIN POWER SERVICE CORPORATION'S STANDARD TERMS AND CONDITIONS ARE INCLUDED AS PART OF THIS AGREEMENT QUANTITY IPSC DESCRIPTION ACCOUNT NUMBER M PART NO. ORDERED UNIT PRICE **EXTENSION** LINE 1 EΑ 1 TEI TO MODIFY PACKING GLAND TO ABB SCANNERS TO 9,356.00 2SGX-402 9,356.00 MAKE THEM WORK. THIS IS TEI FCO #15 03-96033-22 RELEASE # 7 AGAINST SERVICE CONTRACT # S45618 PURCHASE PRIORITY #4 APPRD BY G CROSS *** SERVICE CONTRACT DESCRIPTION *** INSTALLATION OF LOW NOX BURNERS, ANCILLARY HARDWARE, & ASSOCIATED FLAME DETECTION SYSTEMS IN UNIT 2 ****ATTENTION IPSC WAREHOUSE**** PLEASE RECEIVE. PO IS FOR SERVICES, FEES, DUES, PREMIUMS, TUITION, AND MISCELLANEOUS CHARGES. NO MATERIAL WILL BE RECEIVED. DATE REQUIRED 02/27/04 9,356:01 TOTAL COST

- 1. Invoices and correspondence may be mailed to Intermountain Power Service Corporation, 850 West Brush Wellman Rd., Delta, Utah, 84624-9546.
- 2. Acknowledgement is required if shipment will not be made within FIVE days.
- 3. Mark packages or items with IPSC part number and/or P.O. Line number. Show number on invoice and packing slip.
- 4. Vendor must furnish applicable material safety data sheets.
- 5. Add to invoice all applicable federal taxes.

UTAH VENDORS ARE TO ADD TO THE INVOICE ALL APPLICABLE STATE, AND COUNTY TAXES

OUT OF STATE VENDORS, LICENSED TO COLLECT UTAH TAXES. ARE TO ADD TAX OF 6%

UTAH TAXES WILL BE ACCRUED BY IPSC FOR OUT OF STATE VENDORS NOT LICENSED TO COLLECT UTAH STATE TAX

NANCY BENNETT 435-864-4414.

REVIEWED BY NANCY BURENNETT

Jerry,

You received the entire assembly which typically connects to a three inch female coupling. Since you have a threaded pipe already installed there can be only a few options. Your picture Scanner Packing Gland2 is the correct orientation. One option would be to modify the existing pipe and drill holes for the positioning bolts and place the gland cap and packing on the existing pipe. The other option would be to cut the pipe back on the burner and re-thread and provide a female coupling. The bolts in the packing gland are need to keep the pipe centered and lock it down the packing gland cap and packing material is required to seal the assembly.

If you need any additional assistance please contact me at the following:

Regards,

William M. Clark
ABB Inc.
2 Waterside Crossing
Windsor, CT 06095

Phone: (860) 285-9402 Fax: (860) 285-6999 Cell: (860) 559-5673

E-Mail: william.m.clark@us.abb.com

Message from "Jerry Finlinson" <Jerry-F@ipsc.com> received on 02/23/2004 06:37 PM

02/23/2004 06:37 PM

"Jerry Finlinson" <Jerry-F@ipsc.com>

Internal

Sent by 'Jerry Finlinson' <Jerry-F@ipsc.com>

To: <sal@advancedburner.com>, Harry Dohalick/USINY/ABB@ABB_US01, James M Clark/USIMS/ABB@ABB_US01, William M. Clark/USPOA/ABB@ABB_US01

cc: "Howard Hamilton" <howard-h@ipsc.com>, "James Nelson" <JIM-N@ipsc.com>, "Jon Christensen" <JON-C@ipsc com> Subject: Flame scanner packing gland installation difficulties

FYI,

I fouind the flame scanner tube packing glands and tried installing one.

I can't tell which way they are supposed to install. They appear to be missing


a connector or something. If there is a coupler in there then the scanner tip will be about 16 inches back from the turning vanes.

See enclosed photo of the packing gland. Please advise.

Thanks, Jerry

Jerry Finlinson, Engineer Intermountain Power Service Corp 850 West Brush Wellman Rd Delta, UT 84624

file://C:\MASTER%20FILES\WPFILES\IGS03.PRJ\IGS03-04%20Unit%202%20Burners... 8/23/2004



IP7_030629

From: Jerry Finlinson

To: Harry Dohalick; James Clark; william.m.clark@us.abb.com

Date: 2/25/2004 4:32:17 PM

Subject: Re: Flame scanner packing gland installation sample

Bill,

We have modified a flame scanner packing gland pipe as shown in the attached photo.

Please examine and give your approval. We think we'll change it by moving the positioning bolts farther from the burner, closer to the packing gland, so they won't

interfere with insulation. There are about 3.5 threads on the bolt. That should be sufficient. TEI estimates that it will take 30 to 60 minutes per burner to make these modifications.

Give your approval to go ahead like this. They'd like to start this work Thursday morning. Thanks, Jerry

Jerry Finlinson, Engineer
Intermountain Power Service Corp
850 West Brush Wellman Rd
Delta, UT 84624
435-864-6466 fax 0776/6670
jerry-f@ipsc.com

>>> <william.m.clark@us.abb.com> 2/23/2004 9:43:52 PM >>>

Jerry,

You received the entire assembly which typically connects to a three inch

female coupling. Since you have a threaded pipe already installed there can be only a few options. Your picture Scanner Packing Gland2 is the correct orientation. One option would be to modify the existing pipe and

drill holes for the positioning bolts and place the gland cap and packing

on the existing pipe. The other option would be to cut the pipe back on the burner and re-thread and provide a female coupling. The bolts in the

packing gland are need to keep the pipe centered and lock it down the packing gland cap and packing material is required to seal the assembly.

If you need any additional assistance please contact me at the following:

Regards,

William M. Clark ABB Inc. 2 Waterside Crossing Windsor, CT 06095

Phone: (860) 285-9402 Fax: (860) 285-6999 Cell: (860) 559-5673

E-Mail: william.m.clark@us.abb.com

Message from "Jerry Finlinson" < <u>Jerry-F@ipsc.com</u>> received on 02/23/2004 06:37 PM

02/23/2004 06:37 PM Internal

"Jerry Finlinson" <Jerry-F@ipsc.com>

Sent by "Jerry Finlinson" < Jerry-F@ipsc.com >

To: <sal@advancedburner.com>, Harry Dohalick/USINY/ABB@ABB_US01, James M.

Clark/USIMS/ABB@ABB_US01, William M. Clark/USPOA/ABB@ABB_US01

cc: "Howard Hamilton" < howard-h@ipsc.com > , "James Nelson"

<JIM-N@ipsc.com>,

"Jon Christensen" <JON-C@ipsc.com>

Subject: Flame scanner packing gland installation

difficulties

FYI,

I fouind the flame scanner tube packing glands and tried installing one.

I can't tell which way they are supposed to install. They appear to be missing

a connector or something. If there is a coupler in there then the scanner tip will be about 16 inches back from the turning vanes.

See enclosed photo of the packing gland. Please advise.

Thanks, Jerry

Jerry Finlinson, Engineer
Intermountain Power Service Corp
850 West Brush Wellman Rd
Delta, UT 84624
435-864-6466 fax 0776/6670
jerry-f@ipsc.com

From:

<james.m.niziolek@us.abb.com>

To:

"Jerry Finlinson" <Jerry-F@ipsc.com>

Date:

3/5/2004 1:19:43 PM

Subject:

Re: ABB flame scanner full coupling arrived

Jerry,

This looks good. The 3-4 inches in back of the register plate sounds about right per the drawings. Based on the earlier pictures the scanner tip should be sighted through the center of the hole in the register plate and the slot in the turning vanes.

It is not a big deal but before final tightening of the packing gland and the locking bolts I'd push the scanner guidepipe all the way forward into the packing gland. In the picture it looks like it's back 1 to 1.5 inches.

Take care

Jim Niziolek

Message from "Jerry Finlinson" <Jerry-F@ipsc.com> received on 03/04/2004 10:33 PM

03/04/2004

"Jerry Finlinson" <Jerry-F@ipsc.com>

10:33 PM

Sent by "Jerry Finlinson" <Jerry-F@ipsc.com>

To:

James M. Clark/USIMS/ABB@ABB_US01,

James M. Niziolek/USSEV/ABB@ABB_US01,

<arnold.j.piellucci@ussev.mail.abb.com>

